

Experiences of landslide prevention works in Vietnam

*Introduction of Landslide Disaster in Vietnam
and Application of the Japanese Technology of Landslide countermeasures*



Kawasaki Geological Engineering Co., Ltd

Takami KANNO Ph.D./PE.Jp

CONTENTS OF THE PRESENTATION

1. Introduction

ベトナムにおける防災対策の現状

2. Introduction Landslide countermeasure works in Vietnam

ベトナムで行った主な地すべり対策の紹介

① Landslide control work

- *Mon-Seng bridge Landslide, Lao Cai in mountainous areas*
- *Da Lat city Landslides ,Lam Dong occurred in urban area*

② Landslide prevention work

- *Bai Chai Landslides ,Quan Ninh occurred along the road*

3. CONCLUSION

まとめ

Introduction

■ In recent years, increase in various natural disasters as landslide, due to climate changes on a global scale , becomes the serious social problems.


近年気候変動に伴う地すべり災害多発、社会問題化

■ In Vietnam, the serious physical and human damages has been occurring frequently by landslide disasters and it's debris flow which caused by torrential rain.


ベトナムにおいても豪雨に伴い発生した地すべり災害によって申告な人的・物理的な被害が発生している。

**Example of the slope disasters
and the countermeasures
for landslides .**


Classification of Landslides Type




Rotational landslide




Translational landslide




Block slide



Rock fall



Topple



Debris flow

Countermeasure construction of landslide


Surface Drainage
Drilling

Drainage Well


Steel Pipe Pile

Ground Anchor

Drainage Tunnel



Drainage Well



Drainage Drilling




Drainage Drilling on the ground



Lightweight Fill (EPS : foamed styrol)

Embankment to
the head
of landslide





Comparison of disaster prevention budgets between Lao Cai province and Shimane pref

	Lao Cai province in Vietnam	Shimane Prefecture in Japan	Ratio
Area	6,357 km ²	6,707 km ²	
Population	565,700	705,893	
Total Budget	25.3 billion	527.7 billion	1/21
Disaster Prevention Budget	1.3 billion	39.6 billion	1/31
The Ratio of Disaster Prevention Budget/Total Budget	5.00%	7.50%	

The ratio of disaster prevention expenses to the total budget, which is almost the same ratio. However, the total budget in Lao Cai province is 25.3 billion yen in terms of Japanese yen, and 527.7 billion yen in Shimane prefecture. The total budget for Lao Cai province is only about 1/20 or less of Shimane

GDP per capita trends in Vietnam

GDP per capita has doubled in 10 years



Case Studies

Mon-Seng Bredge


Landslide

One of the most highest risk of the landslides
along the National Road Route 4

Location Map of the Survey Area



Design Work of Landslide Countermeasures



Jun.2012





April.2004

History of the Mon-Sen landslide




Nov.2012

Analysis of Topographic Features of Landslides by Terrestrial LiDAR



Preliminary Results of High Density Geophysical Exploration



Design Work of Landslide Countermeasures

Drainage drilling work



Landslide-slope surface protection by log fence



LEGEND




Drainage drilling



Ground surface drainage



Scarp, Knick line




Ground surface drainage



Design Work of landslide countermeasures

法面工 丸太柵工 $L=4,800\text{m}$, 緑化工 (人力種子散布) $A=28,700\text{m}^2$

Drainage drilling work



Case Study

Landslides occurred at urban area in Da Lat city ,April 2017

Location Map





Drainage Well Construction in Vietnam


Kawasaki Geological Engineering Co.,Ltd
T.Kanno PE(Civil).JP/Ph.D

04-27-2021 12:55:09

Situation near the top of the landslide immediately after the landslide in April 2017







Bên trong nhà, vết nứt chạy dọc theo chân tường và trong khu vực bếp

Sụt lún đất ở trung tâm TP.Đà Lạt: Chuyên gia Nhật Bản khảo sát thực địa

05:41 PM - 27/04/2017 | Thanh Niên Online



Chuyên gia Nhật Bản khảo sát thực tế vụ sụt lún đất

Mời chuyên gia xác định nguyên nhân nứt tường, sụt lún nhiều nhà dân tại Đà Lạt

Thứ Năm, 27/04/2017, 14:12:25

Font Size: - + Print



Khu vực xảy ra tình trạng nứt đất trên đường Nguyễn Văn Trỗi.

tuổi trẻ
online



CHÍNH TRỊ - XÃ HỘI | THẾ GIỚI | PHÁP LUẬT | KINH TẾ | SÓNG KHỎE | GIÁO DỤC | ITUYỂN SINH | TH

Chính trị - Xã hội

Thời sự - Suy nghĩ

Phóng sự - Ký sự

Môi trường | Chuy

Trận đấu lớn nhất mùa giải của Mourinho

Nước ngầm gây nứt đất ở trung tâm Đà Lạt

27/04/2017 20:55 GMT+7



TTO - Các chuyên gia địa chất của Đại học Bách khoa TP.HCM, Viện Hàn lâm khoa học Việt Nam và Công ty Kawasaki (Nhật) đánh giá nước ngầm và mưa lớn là tác nhân quan trọng gây nứt đất tại Đà Lạt.




Vết nứt ngang tường tại một căn nhà trên đường Nguyễn Văn Trỗi - Ảnh: M.Vinh



UBND tỉnh Lâm Đồng họp bàn tìm nguyên nhân

Press

Position of reference point for surveying




Landslide Block


Line-2

Line-1




Line-3



80 × 60m



High-Density Electrical Prospecting Results




Landslide monitoring with ground extensometer



Drilling survey and set-up PSG just before the Drainage Well construction in 2020





Drilling results in 2020




**Setup of water level sensor
and PSG observation device
before drilling of the Drainage Well**



Concept of the drainage countermeasure in the Well



Ground leveling work before excavation of Drainage Well(20 March 2021)



Before placing the concrete top plate




Placement of concrete top plate



Remove the formwork after placing
the concrete top plate










04-01-2021 09:02:42

14 April 2021 Sediment runoff behind the sidewall of the drainage well by heavy rain (beginning of heaving)



土砂流出状況






As a countermeasure against heaving, grouting was carried out around the hollowed out Drainage Well.




CURRENT STATUS (1/2)


Filling cavities by Grouting





SECTION 1-1'



SECTION 2-2'



Identification of the heaving area using orthoimages and topographical contour maps created by aerial drone photography




Aerial photography: Kawasaki Geological Co., Ltd.
Image processing: Nakanihon Air Service

Contour diagram of absolute land surface subsidence during the period from 14 May to 26 Jun.

標高テーブル (mm)

番号	最小標高	最大標高	色
1	-260,000	-240,000	■
2	-245,000	-240,000	■
3	-240,000	-235,000	■
4	-235,000	-230,000	■
5	-230,000	-225,000	■
6	-225,000	-220,000	■
7	-220,000	-215,000	■
8	-215,000	-210,000	■
9	-210,000	-205,000	■
10	-205,000	-200,000	■
11	-200,000	-195,000	■
12	-195,000	-190,000	■
13	-190,000	-185,000	■
14	-185,000	-180,000	■
15	-180,000	-175,000	■
16	-175,000	-170,000	■
17	-170,000	-165,000	■
18	-165,000	-160,000	■
19	-160,000	-155,000	■
20	-155,000	-150,000	■
21	-150,000	-145,000	■
22	-145,000	-140,000	■
23	-140,000	-135,000	■
24	-135,000	-130,000	■
25	-130,000	-125,000	■
26	-125,000	-120,000	■
27	-120,000	-115,000	■
28	-115,000	-110,000	■
29	-110,000	-105,000	■
30	-105,000	-100,000	■
31	-100,000	-95,000	■
32	-95,000	-90,000	■
33	-90,000	-85,000	■
34	-85,000	-80,000	■
35	-80,000	-75,000	■
36	-75,000	-70,000	■
37	-70,000	-65,000	■
38	-65,000	-60,000	■
39	-60,000	-55,000	■
40	-55,000	-50,000	■
41	-50,000	-45,000	■
42	-45,000	-40,000	■
43	-40,000	-35,000	■
44	-35,000	-30,000	■
45	-30,000	-25,000	■
46	-25,000	-20,000	■
47	-20,000	-15,000	■
48	-15,000	-10,000	■
49	-10,000	-5,000	■
50	-5,000	0,000	■

地表レベル観測点配置図




The cavity distribution at the bottom of the masonry retaining wall before excavating the liner plate.
Taken on March 19, 2021

Soil Improvement cross section by Grouting

210708 Docu①


HORIZONTAL SECTION OF SEGMENT No. 10



投影断面②



- * The yellow-green circle is a grout boring hole as of May 19.
- * The red circle is the drilling hole plan for this grout.

210707 Additional Emergency Grouting Method (Cement - Bentonite improvement, replacement, filling)





Estimated drawing of the grouting effect around the LP Well

Legend of Grouting improvement and injection

IP1, IP1', IP1'': Filling by mortar injection
 • IP1: Hard enough
 • IP1': Slightly inhomogeneous (soft)
 • IP1'': Weak consolidation

IP3, IP4: Filling by cement-bentonite injection or Improvement
 • IP2: Stage 1 emergency measures
 • IP3: Stage 2 emergency measures (This time)
 • IP3: Stage 3 emergency measures (This time)

Legend

Bs: Filled soil
 Co: Top concrete around the LP Well


Clay (N=4)
 Clay (N=7)
 Clay (N>10)

Geology

--- Groundwater level

Countermeasure against heaving

Load reduction by the EPS method




210726 Docu5


210726 Docu4

A Restoration method for soil removal area by EPS (Styrolfoam)



A'



Displacement prediction of drainage well after installation of bottom concrete



Inclination of the top plate of the catchment well



Displacement stop after installation of bottom concrete

2021.9.27 Drainage Drilling



① Involving artificial ground such as embankment and garbage, weak and soft soil clay layer

SECTION A-A

SCALE : 1/40

Elevation (m)

1005
1000
995
990
985
980
975
970
965

K01 (20m)
GL= 1000.23m

HK03 (20m)
GL= 987.32m

② Heaving zone

Elevation angle=8°
L=35m


Lower Drilling Elevation +1m
angle=6°
L=35m


Original Upper


Change proposal Upper

Original Lower

DESIGN-ADJUST DESIGN








Case Studies


Bai Chai district ,Quan Ninh

Landslides occurred along the road


The status of the area of approach road to Bai Chay bridge, Quang Ninh through the years (2001 - 2016)




08/17/2001 (in the past)



02/25/2010 (after road construction)




02/06/2016 (currently)



05/10/2015 (under the construction on the top)

[MAY 2015]

Before countermeasure work



[AUG 2019]

After countermeasure work





写真3.写真1の①の拡大



写真4.写真1の②、③の拡大



写真5.写真4の③近接写真



写真6.写真4の③地すべり性崩壊頂部



写真 7.断層上の受け盤構造の地層



写真 8.断層下の流れ盤構造の地層



写真 9.断層ガウジを伴う破砕帯




写真 10.断層下に面的に分布する破砕帯




2017/05/16

BAI CHAY SITE INVESTIGATION MAP
SCALE 1:500



BAI CHAY SITE INVESTIGATION MAP

SCALE 1:250



LEGENDS

- Elastic wave investigation line
- Existing boreholes
- New borehole
- Existing targets
- New targets
- Range of steel net


Weather strong
Land slide Block

Weathered
CL-D rock

Weathered
CL rock




		Concrete	Concrete
1	Strong weathered Breccia	強い風化レキ岩	Strong weathered Breccia
			From 0.1 to 0.3 m: Strongly weathering sandstone From 0.3 to 1.0 m: weathering sandstone, white gray color; The cracks filled with reddish brown clay. From 0.95 m to 1.00 m section with large cracks filled with reddish clay material. From 1.00 to 1.7m: weathering and cracking sandstone. From 1.40 to 1.70m section: Large cracks filled with reddish clay material
2		破碎質粘土	Shear clay
			Shear clay (clay with gravel and sand)
3		風化レキ岩	Weathered Breccia
			From 1.8 to 2.0m: weathering and cracking sandstone. From 2.0 to 2.75m: weathering sandstone and pudding-stone. From 2.75 to 3.35m: weathering sandstone and pudding-stone; white gray color
4		破碎質粘土	Shear clay
			Shear clay (clay with gravel and sand)
		風化レキ岩	Weathered Breccia
			From 3.45 to 4.25m section: strongly weathering sandstone and pudding-stone.
		故障箇所 風化レキ岩	Fault gauge
			Fault gauge
5		風化レキ岩	Weathered Breccia
			From 4.50 to 5.5 m section: weathering sandstone and pudding-stone
6		破碎質粘土	Shear clay
			Shear clay (clay with gravel and sand)
7		風化レキ岩	Weathered Breccia
			From 5.6 to 6.35 m: weathering sandstone and pudding-stone. From 6.35 to 7.20 m: weathering sandstone and pudding-stone; hardly stone. (the crack filled with reddish clay material) From 7.20 to 8.20 m: weathering sandstone and pudding-stone; hardly stone (the crack filled with reddish clay, sand and quartz material) From 8.20 to 9.0 m: weathering sandstone and pudding-stone; hardly stone (the crack filled with reddish clay, sand and quartz material)
9		故障箇所 風化レキ岩	Fault gauge
			Fault gauge
10		風化レキ岩	Weathered Breccia
			From 9.2 to 10.45m: weathering sandstone and pudding-stone; hardly stone (the crack filled with reddish clay material) From 10.45 to 10.70m section: The crack filled with reddish clay, sand and quartz material.



土質定数						
No.	地層	地質	湿潤重量 γ_t (kN/m ³)	飽和重量 γ_{sat} (kN/m ³)	粘着力 C (kN/m ²)	内部摩擦角 ϕ (°) $\tan \phi$
1	D		26.00	26.00	50.00	38.0000 0.781285
2	I _s		26.00	26.00	50.00	38.0000 0.781285
3	D-CL		26.00	26.00	50.00	38.0000 0.781285
4	CL		26.00	26.00	100.00	38.0000 0.781285
5	CM		26.00	26.00	200.00	40.0000 0.839099
6	CM		26.00	26.00	200.00	40.0000 0.839099

※ 水の単位体積重量 γ_w : 10.000 (kN/m³)





Conclusion

■ *Suggest the importance of disaster prevention and mitigation, that should take some measures before the serious damages will occur (ex:hazard map).*

防災・減災に重要なのは、被害を受ける前に事前に手を打っておくこと(ハザードマップ)

■ *An important point for Japanese companies doing business in Vietnam is to be able to deploy as many solutions as possible.*

日本の会社がベトナムで業務を行うためには、できるだけ多くのソリューションを有していること。

■ *It is also important to provide technical solutions that allow us to obtain a large amount of geological information that will serve as the basis for construction before construction.*

そして、施工前に施工に必要な多くの地質情報を得るための技術ソリューションを提供できること。

■ **And last , it is important have enthusiasm and the ability to complete the project.**

最後に重要なのは熱意とプロジェクトをやりとげる実行力です。

Thank you for listening !